

Attachment #1

Photographic Log



Photo #1: Container storage area outside the Facility with pieces of broken circuit boards and used electronic appliances.




Photo #2: Overview of the Outside Container Storage Area.



Photo #3: PCs that were shrink-wrapped and on pallets in Building #1.



Photo #4: Flat-screen televisions shrink-wrapped and stored on a pallet in Building #1.




Photo #5: Bundles of low-grade circuit boards wrapped in cardboard and stored on pallets.




Photo #6: Used computer network devices and CPUs shrink-wrapped and on pallets in Building #1.



Photo #7: Overview of used networking devices, CPUs, and unused surgical equipment in Building #1.



Photo #8: Close-up of unused surgical needles taken out of a 55-gallon drum.



Photo #9: Close-up of the labels on the 55-gallon drums that contain unused medical equipment. The drums were dated and labeled with the words “scrap.”



Photo #10: Close-up of the unused, packaged scalpels stored in a 55-gallon drum in Building #1.



Photo #11: Overview of Building #1.



Photo #12: Open 55-gallon drum containing used batteries in Building #1 labeled with the words "Batteries."




Photo #13: Contents of the 55-gallon drum containing used batteries seen in Photo #12 above.




Photo #14: Overview of the shelf containing a used aerosol can next to the entrance of Building #1.




Photo #15: Bale machine in the background, and an open container of scrap plastic in the forefront.



Photo #16: Close-up of the contents of the container, as seen in Photo #15.



Photo #17: Pre-crusher with a container of scrap sweepings in the forefront.



Photo #18: Open cubic yard boxes under the Sorting Line.



Photo #19: Open cubic yard box containing broken circuit boards under the Sorting Line.



Photo #20: Overview of the Sorting Line.



Photo #21: Uncontained scrap material on the ground located near the Sorting Line.



Photo #22: Open 30-gallon container labeled with the word "batteries" located on top of the Sorting Line.



Photo #23: Close-up of the spent batteries in the container as see in Photo #22 above.




Photo #24: Close-up of the product label from a SLAB contained in the 30-gallon drum seen in Photo #22 above.




Photo #25: Overview of the ring crusher machine.



Photo #26: Close-up of the baghouse portion of the ring crusher.



Photo #27: 3 unlabeled 55-gallon drums located in Building #3.




Photo #28: 55-gallon drum of used oil fitted with a funnel located in Building #3.



Photo #29: Several small open containers of used oil in Building #3.



Photo #30: Several aerosol cans that were still in-use on a shelf in Building #3.



Photo #31: Overview of the Metal Hanger Building.




Photo #32: Inside view of the Metal Hanger Building full of shredded scrap and unprocessed material.




Photo #33: Pallets of universal power supplies.



Photo #34: SLABs stored on a pallet and labeled with a sign "Lead Acid Batteries for Recycling."



Photo #35: Intact CRT monitor stored on a table in Building #2.



Photo #36: Open 55-gallon drum of laptop batteries labeled with the words "Laptop Batteries."




Photo #37: Close-up of the laptop batteries in the 55-gallon drum as seen in Photo #36 above.




Photo #38: Container storage area located next to Building #2.




Photo #39: Open 55-gallon drum partially filled with high voltage devices located outside Building #2.



Photo #40: Close-up of the product label on one of the high voltage devices seen in Photo #39 above.




Photo #41: Used electronics accumulated outside Building #2 on the ground and in cubic yard containers.



Photo #42: Broken circuit boards that were piled on the ground and covered with a blue tarp outside Building #2.



Photo #43: Broken circuit boards that were piled on the ground and covered with a blue tarp outside Building #2.



08/24/2011 12:39

Photo #44: Overview of the Storage Building.




Photo #45: Used, intact CRT television in the Storage Building stored on the ground.



Photo #46: Unopened boxes of fluorescent lamps in the Storage Building.



Photo #47: Open cubic yard container of CRT monitors and other material in the Storage Building.



Photo #48: Open cubic yard container with CRTs, as seen in Photo #47 above.



Photo #49: Containers of circuit boards in the Storage Building.